

WinSMITH Weibull and WinSMITH Visual Instruction Manual and Guide

**Paul Barringer, P.E.
Barringer & Associates, Inc.
P.O. Box 3985
Humble, TX 77347-3985**

**Phone: 1-281-852-6810
FAX: 1-281-852-3749**

**Email: hpaul@barringer1.com
Web: <http://www.barringer1.com>**



WinSMITH Weibull and WinSMITH Visual Software Instruction Manual and Guide,

First Edition

All rights reserved. Reproduction or translation of any part of this work beyond that permitted by Section 107 or 108 of the 1976 United States Copyright Act without permission of the copyright author is unlawful. Requests for permission should be addressed to the author(s).

Weibull Methodology by Robert B. Abernethy

536 Oyster Road
North Palm Beach
Florida 33408-4328
Phone: 561-842-4082
FAX: 561-842-4082
E-mail: weibull@worldnet.att.net

Software by Wes Fulton

Fulton Findings(TM)
1251 W. Sepulveda Blvd. PMB-800
Torrance, CA 90502
Phone: 310-548-6358
FAX: 310-548-6358
E-mail: wes@weibullnews.com
Website: <http://www.weibullnews.com>

Presentation by Paul Barringer

Barringer & Associates, Inc.
P.O. Box 3985
Humble, TX 77347-3985
Phone; 281-852-6810
FAX: 281-852-3749
E-mail: hpaul@barringer1.com
Website: <http://www.barringer1.com>

Distributed by Dr. Abernethy, Wes Fulton, and Paul Barringer

Printing History: (Every printing includes updated material.)

First Edition First Printing February 2002, Second Printing April 2002.

Trademark and Copyright Notice: Laserjet, HPGL, and Deskjet are trademarks belonging to Hewlett-Packard, Inc. PC/XT/AT/PS2 are trademarks belonging to IBM, Inc. Windows, MS-DOS, Excel, Powerpoint and Word are trademarks belonging to Microsoft Corporation. Lotus is a trademark belonging to Lotus Development Corporation. The New Weibull Handbook is copyrighted by Robert Abernethy. PlayTIME, Fulton Findings, WeibullNEWS, WinSMITH, and SuperSMITH are trademarks belonging to Wes Fulton. All other trademarks and copyrights mentioned herein belong to their respective business units.

Preface

This manual is intended as a home study guide or a 1-day training class in how to use WinSMITH Weibull and WinSMITH Visual software for those who want more details about the common features of the software. This manual does not include the more elaborated subjects and details offered in PlayTIME for SuperSMITH.

WinSMITH Weibull is a stand-alone menu-driven probability plotting/analysis software program. The program provides for best-practice Weibull analysis including many techniques not available elsewhere. WinSMITH Weibull software is the defacto standard for life data analysis, prediction, and for evaluating variability and uncertainty in practically all industries. Capabilities of WinSMITH Weibull include Weibull, normal, lognormal, and Gumbel (lower and upper) distributions, and variations of these, as well as likelihood plotting, confidence plotting, design comparison, probabilistic analysis, outlier detection, optimum replacement, failure forecasting, test substantiation planning, accelerated testing, and mixture analysis.

WinSMITH Visual is a general plotting/analysis program with complimentary capability to WinSMITH Weibull. Capabilities of WinSMITH Visual include general function plotting, transforms, curve fitting, aggregate cumulative hazard (ACH) plotting, and Crow/AMSAA (Duane) reliability growth plotting. The primary functions of the older (for MS-DOS) WeibullSMITH™, BiWeibullSMITH™, and MonteCarloSMITH™ programs are included in WinSMITH Weibull. WinSMITH Weibull also includes new mixture analysis capability and process reliability analysis calculations.

WinSMITH Weibull and WinSMITH Visual software offer more useful options and capabilities than any other current life data analysis program, although it is extremely compact in size. This wide ranging usefulness is due to the many applications in industries including automotive, components, aerospace, medical, electronic, electric power, petrochemical, nuclear, rail transport, dental, materials analysis and others. The compact program size allows easy transfer/use over networks. This training manual is intended to illustrate most of the frequently used capability and many of the applications. Hopefully, it is helpful for both novice and expert.

The reference book for all the material herein is The New Weibull Handbook, authored and published by Dr. Robert B. Abernethy. WinSMITH Weibull and WinSMITH Visual software are written by Wes Fulton.

You can obtain the latest version of DEMO software for no-charge downloads from Wes Fulton's website (<http://www.weibullnews.com>) or from Paul Barringer's website (<http://www.barringer1.com>). You can also download an electronic copy of the latest WeibullNEWS™ newsletter published by Wes Fulton and Dr. Abernethy.

See the Barringer website for general introduction to reliability in practice, the latest Problem of the Month, and details from Dr. Abernethy's library posted as no-charge downloadable files concerning Weibull Analysis.

Table of Contents

General Information

Software Setup Details.....	Page	ix
Getting Started After Software Is Loaded.....	Page	x
WinSMITH Weibull Probability Plotting Software Icons.....	Page	x
WinSMITH Visual General Plotting Software Icons.....	Page	xi

WinSMITH Weibull Software

1. Manual Data Input	1
2. Make A Probability Plot.....	2
3. How To Interpret The Weibull Probability Plot.....	3
4. How To Import One Column Of Data From Excel To WSW.....	3
5. How To Import Two Column Data From Excel With Suspensions.....	4
6. Data Entry Reminder.....	5
7. Icons.....	5
8. Quick Plot Using Data From Random Draw (Monte Carlo) Simulation.....	6
9. Confidence Interval Icon.....	7
10. Likelihood Ratio Test Icon.....	7
11. New Page Icon.....	9
12. Setup Icon.....	9
13. Printer/Output Icon.....	10
14. Another Quick Analysis Using Optimum Replacement Intervals.....	11
15. High Resolution Graphical Outputs.....	12
16. Adding Labels To Graphs.....	14
17. Printing Graphs.....	16
18. The Calculator.....	18
19. Demonstrate/Sample Data Input.....	25
20. Distribution Analysis.....	26
21. Prediction-Precise Reading From Plot + Likelihood Plot.....	28
22. Failure Forecast For Quantity Expected (Abernethy Risk Analysis).....	28
23. Test Requirements.....	32
24. Help File.....	35
25. Method/Input.....	36
26. Only Line...No Data.....	37
27. Three Parameter Curve Fit.....	37
28. WeiBayes MLE (1-parameter).....	39
29. Zoom/Hide (Point/Set/Quantity).....	40
30. Additional FF Analysis.....	42
31. Accelerated Test/Degradation (PEFV).....	42
32. Mixture + Process Reliability.....	45
33. Information Display.....	48
34. Batch Operation.....	48

Appendix A – The WinSMITH Weibull Icon Tour	51
• New Plot	51
• PC Icons.....	51
• Open File Folder.....	53
• Save File.....	54
• Plot/Report.....	54
• Calculator.....	56
• Printer.....	56
• Dice (demonstrate/sample).....	58
• Distribution Analysis.....	59
• Optimum Replacement Interval.....	60
• Predict-Precise Plot Reading.....	61
• Quantify Expected (Abernethy Risk) Analysis.....	62
• Test Requirements.....	64
• Help?	65
• Confidence Intervals.....	65
• Labels.....	67
• Methods.....	68
• Only Line.....	70
• t Zero – 3 Parameter.....	70
• WeiBayes – 1 Parameter.....	71
• Zoom/Hide.....	72
• Additional Fulton Findings Programs.....	73
• Accelerated Test/Degradation.....	73
• Mixture.....	74
• Information.....	75

WinSMITH Visual Software

1. Manual Data Input.....	76
2. How To Make A Plot.....	76
3. How To Import X-Y Data From Excel.....	78
4. Data Entry Reminder.....	78
5. Make A Crow/AMSAA Plot.....	79
6. Icons.....	79
7. New Page.....	83
8.	

Appendix B – The WinSMITH Visual Icon Tour	95
• New Plot	95
• PC Icon.....	95
• Open File Folder.....	97
• Save File.....	98
• Plot/Report.....	98
• Calculator.....	99
• Printer.....	102
• Dice Icon(Demonstrate/Sample).....	102
• Math Function Icon.....	102
• Crow/AMSAA (Duane).....	103
• Predict.....	104
• Help.....	105
• Plot Type/Curvee	105
• Labels.....	105
• Curve Fit.....	106
• Transform (Make Changes To Data).....	107
• Zoom/Hide (Point/Set/Quantity).....	108
• Additional FF.....	108
• Information.....	108

WSW-WSV Get Software Ready

Software Setup Details-

WinSMITH™ Weibull (WSW) and WinSMITH™ Visual (WSV) are two different programs. They have different installation diskettes. Assume the installation diskette is placed in the A: drive. Assume the program will be setup into the C:\SMITHW directory (the setup program will make this directory). The programs are 32-bit Windows programs. These more advanced programs will not run on the original Windows 3.0 or Windows 3.11; however they will run on all other higher level Windows systems including Windows 95, Windows 98, Windows ME, Windows NT workstation or server, Windows 2000 workstation or server, and Windows XL. RAM requirements are modest and space required on the hard drive is also modest. **Note to LAN managers:** perform the entire setup on the machine you intend to use (do not set it up on one machine and copy the files to another machine as the installation program adds programs to the systems directories).

For each program, run its SETUP.EXE file on the diskette provided. From Windows, select START and then RUN and enter A:\SETUP.EXE after the path locating SETUP.EXE. Or you can use BROWSE to locate SETUP.EXE on the disk, then run the SETUP.EXE program. Follow the on-screen instructions given during SETUP.

Starting Instructions: Start the software from the main Windows screen by first selecting START. Then select and run the appropriate SuperSMITH™ software program as listed either above the PROGRAMS selection or by first selecting PROGRAMS. You should initially see the opening screen with one button displaying “<Y> Yes I Agree To The Above” and another button displaying “<X> Exit”. Choose “<Y> Yes I Agree To The Above” to accept the usage disclaimers shown and continue to the main screen. The main screen displays all of the options available in the software with icons and menu items for each choice plus a data spreadsheet and a results window.

Usage Instructions / On-line User Manual: The use of the software is described in detail in the on-line HELP file user manual that comes with the software. To access the electronic user manual, choose the HELP option from the main screen. The New Weibull Handbook® (ISBN 0-9653062-1-6) by Dr. Robert B. Abernethy is the reference manual for the methodology in our Weibull-related software. This handbook is the standard reference used to describe Weibull technology and is available separately.

Server/LAN Operation: Server/LAN use is completely acceptable given that *the purchaser's network administration must limit access to one simultaneous user per purchased copy*. The software reads information from the command line (can be different for each user) to assist LAN operation. Add “-cXXX” to the command line to store user-specific configuration files into path XXX. Add “-tYYY” for temporary file storage location as path YYY. Include a space between entries. Please see the HELP file in the software for more command line examples.

Getting Started After Software Is Loaded-

Here are a couple of tips about the appearance of the software differences. For WinSMITH Weibull (the probability plotting and analysis software) refer to Figure 1:




Figure 1: WinSMITH Weibull

Figure 2 shows the icons for WinSMITH Weibull.




Figure 2: WinSMITH Weibull Icon Definitions

Look at the differences for WinSMITH Visual (the general scientific graphing and Crow/AMSAA plotting software), refer to Figure 2. Notice the name Visual and fewer icons than for WinSMITH Weibull.





Figure 3: WinSMITH Visual

Figure 4 shows the icons for WinSMITH Visual.



Notice each software has a spreadsheet for data entry, a thumb size graph, and special icons for performing the calculation or routine chores. If you prefer, you can use the pull-down menus to perform the operations.

WinSMITH Weibull Software (An Excerpt From The Manual)-

1. Manual Data Input-

The spreadsheet becomes active when you click in the sheet (just like occurs with Excel™) and it changes appearance to give you clues the sheet is active, see Figure W1.




Figure W1: WinSMITH Weibull Spreadsheet

Use the active data entry box to enter data (8, 14, 17, 21, 33—you do not need to order the data) by use of the edit box such as 8, **Enter**, 14, **Enter**,...33, **Enter**. Check for data input errors by viewing the data **BEFORE** you move the mouse over the thumbnail graph or return to the main screen. When the mouse is moved over the graph, the data are automatically ordered and you loose the input arrangement. If the data entry is a suspension, enter a “—“ (minus) sign before the number. See Figure W2 for data appearance before and after entry.




Figure W2: WinSMITH Weibull Spreadsheet During And After Data Entry

2. Make A Probability Plot-

Using the spreadsheet data in Figure W2, move the mouse pointer to the small size plot. The thumbnail plot appears as shown in Figure W3.




Figure W3: WinSMITH Weibull Thumbnail Plot

Enlarge the thumbnail plot, by mouse click. It will go to full screen as in Figure W4.




Figure W4: WinSMITH Weibull Full Scale Plot

Remove the full screen plot, by touching the ESCAPE key or left click with the mouse.

3. How To Interpret The Weibull Probability Plot-

In Figure W4, notice:

- The probability plot is a **Weibull** plot, and it uses **rank regression** calculations methods
- **Shape factor β** (line slope β is 2.007 --it is literally the rise over run calculation for 1:1 graph paper and this is not 1:1 paper) suggests a component wear out failure mode. The shape factor β is dimensionless.
- **Location factor η** (characteristic life η is 21.4 using raw data units [hours, years, months, cycles, etc.]) occurs where the trend line crosses the 63.2% double line for the cumulative distribution function (CDF).
- The plot contains **5 pieces of data = n** and **0 suspensions = s**.
- The **coefficient of determination $r^2 = 0.981$** , is a measure of goodness of fit. It says the straight line explains 98.1% of scatter in the data.
- The graph was made on the **date** of January 13 , 2002 \rightarrow M01D13YR2002
- The **small “1”** in the upper right hand corner by the triangle symbol is the legend for the graph. WSW graphs can contain up to 10 trend line data sets.

Ten percent (B_{10} or L_{10}) of the population is expected to fail in 7 units of time or less—this means 90% of the population will exceed 7 units of time. Ninety percent of the population will fail in 32.4 units of time or less. Thus 90% - 10% = 80% of the population is expected to fail in the range of 7 units of time to 32.4 units of time.

4. How To Import One Column Of Data From Excel To WSW-

A single column of Excel data can be imported into WinSMITH Weibull in two steps as shown in Figure W5:




Figure W5: WinSMITH Weibull Data Import From Excel

The pasted results will look like the data shown in the right hand side of Figure W5.

5. How To Import Two Column Data From Excel With Suspensions-

In Excel, make sure the **left hand column contains age to failure** and the **right hand column contains the quantity** (number of occurrences) of data. Copy the data from Excel and paste into WinSMITH Weibull **using the paste icon**—then the WinSMITH Weibull software will recognize the data requires some decisions and select the option that the two column data has “quantities” in the right hand using **Option B** to get the data shown in Figure W6:




Figure W6: WinSMITH Weibull Data 2-Import From Excel

separate columns. Multiple columns can be consolidated into a single column for insertion into WinSMITH Weibull using Excel’s CONCATENATE function.

Figure W6 has suspended or censored data as evidenced by the “—“ (minus) sign in Excel which translates to the “>” sign as shown in Figure W6. Thus WinSMITH Weibull handles the conversions automatically.

Complicated spreadsheets may have age and quantity in widely separate columns. Data in column AA in the Excel spreadsheet is Age*Quantity for import as a single column of data for pasting directly into WinSMITH Weibull.

An equivalent Excel consolidation function involves use of the &-operator for concatenation. For example =concatenate(c1,”*”,q1) in Figure W7 is equivalent to =(c1&”*”&q1) where the parentheses are optional with the &-operator but are shown here for clarity just as might occur for clarity in an Excel spreadsheet.

The concatenation function works well when many columns of data must be imported into WinSMITH Weibull as columns of frequency data (Datum x Quantity).

6. Data Entry Reminder-

When the mouse pointer is on the spreadsheet, a dialog box appears as a reminder concerning data format. The dialog tells you the data should be in the format of Data x Quantity [-Datum = Suspension]. The reminder dialog box is shown in Figure W8.




Figure W8: WinSMITH Weibull Tooltip Reminder Box

End of the excerpts from the training manual

...

WinSMITH Visual Software (Excerpts From The Manual)-

1. Manual Data Input-

The spreadsheet becomes active when you click in the sheet (just like occurs with Excel and it changes appearance to give you clues the sheet the sheet is active as shown in Figure V1.




Figure V1: WinSMITH Visual Spreadsheet

Data is enter into the plotting software in the format X-scale * Y-scale * Quantity (the quantity feature is also used for a Z-scale 3-dimensional plot)—when the quantity is not specified, then the default value of “1” is supplied by the software. Unlike the probability plotting software, the data does not change after entry. If data is input in the wrong format (e.g., Y-scale*X-scale a data transform icon is discussed below to unscramble the error without data re-entry.

Use the active box on the spreadsheet to enter data (2x1, 4x2, 6x3, 8x4, 10x5—the data must be in the sequence your want it to appear on the plot following the format X-data * Y-data * Quantity(Z-data)). For data entry, you can use the asterisk or the “x” or “*” key to separate the data for use by the software. Input the data as 2*4, **Enter**, 4*2, **Enter**...10*5, **Enter**. The data will appear as shown in Figure V2.




Figure V2: WinSMITH Visual Spreadsheet Data Entry Format

2. How to make a plot-

When you have finished data entry, move the mouse over the thumbnail blank screen and the plot will appear in Figure V3. as data points and without trend lines. You can connect the dots by use of the Plot Type icon (bottom row, left icon) and choose curve type as point + line, line only, or point only. If you prefer, you can fit the data to a variety of different math models found under the Curve Fit icon on the bottom row, third from the left. Interpretation of the plot requires no comment.




Figure V3: WinSMITH Visual Spreadsheet Thumbnail Plot

Enlarge the thumbnail plot in Figure V3, by mouse click and it will go full screen as shown in Figure V4.




Figure V4: WinSMITH Visual Spreadsheet Full Scale Plot

3. How to Import X-Y data from Excel-

Make sure the data columns in Excel are **X-data** in the **left column** and **Y-Data** in the **right column**, the highlight the cells and copy. To paste the two data columns into WinSMITH Visual, click on the paste pot icon (DO NOT do a typical Windows paste into WSV because it won't work!!) and select option B from the paste into the spreadsheet dialog box which tells the software how to handle the data. The four steps are shown in Figure 5.




Figure V5: WinSMITH Visual Copy/Paste From Spreadsheet

You can also use the Excel concatenate function to take multiple columns of data and prepare a single column import using option A in Figure 5 during import—the concatenate function is explained in the WinSMITH Weibull section of this manual.

4. Data Entry Reminder-

When the mouse pointer is on the WinSMITH Visual spreadsheet, a dialog box appears as a reminder concerning data format. The dialog tells you the data should be in the format of X-Data x Y-Data x Quantity. The reminder box is shown in Figure V6.

In case your software does not have a tooltip dialog box, it may have been turned off. To restore the tooltip, go to the bottom row of icons and select the right hand icon. Under the icon choose option I to restore the tooltip box.





Figure V6: WinSMITH Visual Tooltip Reminder Box

5. Make A Crow/AMSAA Plot-

The Crow/AMSAA plot in log-log format produces a straight line for stable processes as a naturally occurring series of events (the trend line models the process and just not the system). The task of reliability engineering improvements is to put cusps on the trend lines by make improvements so as to reduce safety problems and reduce costs. Thus some judgment is required in selected the trend lines and where line segments start-stop. Also note that MTBF and cumulative failure rate go with repairable systems, and MTTF and instantaneous failure rate go with non-repairable systems.

When the line slope on the Crow/AMSAA plot of cumulative failures vs cumulative time is $\beta-1$ the process is called a homogenous Poisson process, and if $\beta \neq 1$ the process is called non-homogenous.

The following explains how to interpret the Crow/AMSAA plots under the C/A icon with options. C/A data can only have suspensions at the end of the dataset where the data is entered with suspended time and the same number of failures as last reported (eg, ...1000*4, 1050*4). 

The Crow/AMSAA technique has three widely used methods and two less widely used rates, each with cumulative time on the X-axis and most produce straight lines for stable processes on log-log plots:

1. **Cumulative failure events vs cumulative time**—this is the default method which produces a line slope of β (if $\beta < 1$ failures are occurring more slowly, if $\beta \sim 1$ no change in the failure rate, and if $\beta > 1$ then failures are occurring more quickly) and λ which is the Y-axis intercept identifying MTBF or MTTF = $1/\lambda$. This is the WinSMITH Visual **default method** involving a nose count of events and time. It is useful for predicting future failures and identifying cusps where significant events have occurred. [$N(t) = \lambda t^\beta$]
2. **Cumulative MTBF or MTTF vs cumulative time** which requires a transform of the Y-axis and thus the actual line slope of the trend line is $1-\beta$. This is **Option T** for WinSMITH Visual. This method requires a transform of the Y-axis (cumulative time)/(cumulative failures). The direction of the curve is a pointer for audiences with attention deficiencies: up for improvements, down for deterioration, and sideways for no change in reliability. [$M(t) = (1/\lambda)t^{1-\beta}$]
3. **Instantaneous failure rate vs cumulative time** which is **Option R + Option I superimposed** for WinSMITH Visual. The line slope is $\beta-1$. This method is often helpful for development activities. [$c(t) = \lambda \beta t^{\beta-1}$]
4. **Instantaneous MTBF or MTTF vs cumulative time.** This is **Option T + Option I superimposed** for WinSMITH Visual. The trend line slope is $1-\beta$. [$m(t) = (1/\lambda \beta)t^{1-\beta}$]
5. **Cumulative failure rate vs cumulative time** which is **Option R** for WinSMITH Visual. The line slope is $\beta-1$. [$C(t) = \lambda t^{\beta-1}$]

The most used features are 1), 2), and 3). Often you will see the term $\alpha = 1-\beta$ in European literature.

Suppose we have the following data set:

Cumulative time:	316.2	752.1	1248.6	1788.9	2364.4	2969.5	3600.6	4254.6	4929.5	5623.4
Cumulative failures:	1	2	3	4	5	6	7	8	9	10


What are β , λ , what do the symbols mean, and when will failure number 11, 12, 15, and 20 occur?

Enter the data, click on the C/A icon, view the plot, interpret the data, and click the 2nd tab for failures.

Figure V7 shows the main screen with a Crow/AMSAA plot and the results,

Click on Option E under the C/A icon will show the failure trends for the graph in Figure V7 into the future which is the basis for a “fearless forecast” about failures which will occur unless action is taken to correct the trend line. The extrapolated line is shown in Figure V9. Remember for Figure V9, the plot

will always increase upward with more failures and the best you can hope for is a significant improvement which would incur large intervals between failures which would cause the line to break sideways. If the trend line for Figure V9 moves upward rapidly it signifies bad news with deteriorating reliability and more failures coming faster which is an unhappy situation.



Clicking on Option T under the C/A icon transforms the Y-axis from cumulative failures to (cum failures)/(cum time). For this case of $\beta < 1$ the trend line will point upward (the desired direction) as shown in Figure V10.

Option T's transform will allow the trend line to point upward or downward as indicated by the happy/sad faces. When no improvements occur, the line will move horizontal.

Figure V10: WinSMITH Visual Crow/AMSAA Cumulative MTBF Plot

The third option frequently used for display of reliability growth involves the instantaneous failure rate which is obtained from Option T along with Option I for the instantaneous trend line. The instantaneous line and the MTBF line will be concurrent if the condition of no-change $\beta = 1$ occurs, however, if $\beta < 1$, the instantaneous line will lie above the MTBF trend line; and likewise if $\beta > 1$, the instantaneous trend line will lie below the MTBF line. The transformed MTBF line and the instantaneous trend line are shown in Figure V11.




Figure V11: WinSMITH Visual Crow/AMSAA Cumulative MTBF Plot + Instantaneous Failure Rate

In Figure V11, projecting the trend line downward and to the left will show that at time 1 on the log scale the trend line will cross 100 which is equivalent to $\lambda = 0.01$ for the failure rate. Also since the system is improving the instantaneous failure rate is also growing as displayed above the MTBF trend line.

The faster the growth in reliability the greater is the involvement by the development team to introduce improvements and to keep them in place so the instantaneous failure rate

plot clearly shows growth opportunities (the gap between the lines) derived from making improvements.

Other options under the C/A icon allow you to have the display to fit your needs such as: the rate of failure occurrences (Option R), the survival transform which is 1- Rate (Option S) which will produce a curved line of both survival and MTBF, and other options to be discussed later.

...

End of excerpts from the training manual

For more details you will need to purchase the WinSMITH Weibull and WinSMITH Visual Instruction Manual and Guide.

Contact Barringer & Associates at:

<http://www.barringer1.com>

Phone: 1-281-852-6810

FAX: 1-281-852-3749

Email: hpaul@barringer1.com